



9/12/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 8/31/00
EPA ID # / Manifest: OHSFN0508038 / 00007
Job Control #: 00 - 679

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

EPA Region 5 Records Ctr.



388231

07278 / 679

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O.H.S.F.N.O.5.0.8.0.3.8	Manifest Document No. 00007	2. Page 1 of 2
3. Generator's Name and Mailing Address US EPA Region 5 (JEFFERSON PROCESSING) 4234 County Rd 74 77 West Jackson Blvd Mingo Junction, OH 43938				
4. Generator's Phone () 740-284-1515				
5. Transporter 1 Company Name Hazmat Environmental Group Inc		6. US EPA ID Number N.Y.D.9.8.0.7.6.9.9.4.7		
7. Transporter 2 Company Name		8. US EPA ID Number		
9. Designated Facility Name and Site Address Safety-Kleen (PPM) Inc. 1875 Forge St. Tucker GA 30087		10. US EPA ID Number G.A.D.9.8.0.8.3.9.1.8.7	A. Transporter's Phone 716-827-7200 B. Transporter's Phone C. Facility's Phone 800-500-7824	
11. Waste Shipping Name and Description		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol
a. NON-DOT, NON-Regulated, NON-PCB, Mineral Oil		0.01	TT	1.8.39.6 K
b.				
c.				
d.				
D. Additional Descriptions for Materials Listed Above A. NON-PCB oil Date removed from service for disposal 8-30-00		E. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information In case of spill, dike and contain. 24hr emergency response# 800 424-8802				
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.				
Printed/Typed Name Thomas Cook		Signature [Signature]		Month Day Year 8/30/00
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name Edward J. Hill		Signature Edward J. Hill		Month Day Year 08/30/00
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		Month Day Year
19. Discrepancy Indication Space Rec'd 11a) 5697 gal (19,370 Kg) @ca				
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name David Campbell		Signature David Campbell		Month Day Year 08/31/00

ORIGINAL-RETURN TO GENERATOR

12-BLS-C6 Rev. 9/92

PCB MANIFEST CONTINUATION SHEET

SAFETY-KLEEN

(PPM PCB SERVICES)

**MUST ACCOMPANY
ALL UNIT MANIFEST**

COMPANY NAME

JEFFERSON PROCESSING CUS EPA REGION 5

PAGE

2

OF

2

MANIFEST DOCUMENT #

DATE _____

830-00

[illegible]

I CERTIFY THAT WITH THE EXCEPTION OF WEIGHTS, THE ABOVE INFORMATION IS TRUE AND ACCURATE

GENERATOR SIGNATURE

GENERATOR PRINTED NAME

DATE _____

DISTRIBUTION - WHITE & YELLOW SAFETY-KLEEN, PINK GENERATOR



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 679

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/8/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00007

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	375	1275.0

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: 
Robert J. Germon
Facility Manager



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 679

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/7/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00007

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	5322	18094.8

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: 
Robert J. Geron
Facility Manager



9/12/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 8/31/00

EPA ID # / Manifest: OHSFN0508038 / 00006

Job Control #: 00 - 678

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C Daniel

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

07278/678

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. OH S F N O 5 0 8 0 3 8		Manifest Document No. 000006	2. Page 1 of 2		
3. Generator's Name and Mailing Address US EPA Region 5 (JEFFERSON PROCESSING) 4234 County Rd 74 17 W JACKSON BLVD Mingo Junction, OH 43938		4. Generator's Phone 740-284-1515					
5. Transporter 1 Company Name Hazmat Environmental GROUP INC		6. US EPA ID Number NYD 980769947					
7. Transporter 2 Company Name		8. US EPA ID Number					
9. Designated Facility Name and Site Address Safety-Kleen (PPM) Inc. 1875 Forge st. Tucker GA 30087		10. US EPA ID Number GAD 980839187		A. Transporter's Phone 716-827-7200			
				B. Transporter's Phone			
				C. Facility's Phone 800-500-7824			
11. Waste Shipping Name and Description a. NON-DOT, NON-regulated, NON-PCB Mineral Oil b. c. d.				12. Containers		13. Total Quantity	14. Unit Wt/Vol
				No.	Type		
				001	TT		
D. Additional Descriptions for Materials Listed Above A NON-PCB Oil Date removed from service for disposal 8-30-00				E. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information In case of spill, dike and contain. 24hr emergency response# 800 424-8802							
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.							
Printed/Typed Name Thomas Cook				Signature <i>[Signature]</i>		Month Day Year 08 30 00	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name Robert Campbell				Signature <i>[Signature]</i>		Month Day Year 08 30 00	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space Rec'd 11a) 4023 gal (13,678 Kg) @ca							
20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name David P. Campbell				Signature <i>[Signature]</i>		Month Day Year 08 31 00	

ORIGINAL-RETURN TO GENERATOR

12-BLS-C6 Rev. 9/92

**MUST ACCOMPANY
ALL UNIT MANIFEST**

DATE 8-30-00

DISTRIBUTION - WHITE & YELLOW SAFETY-KLEEN, PINK GENERATOR

DATE 8/3/02



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 678

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/6/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00006

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	1299	4416.6

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: Robert J. Germon
Robert J. Germon
Facility Manager



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 678

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/7/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00006

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	2724	9261.6

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: 
Robert J. Germon
Facility Manager



9/12/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 9/1/00

EPA ID # / Manifest: OHSFN0508038 / 00005

Job Control #: 00 - 681

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

07278/681

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O H S F N O 5 0 8 0 3 8	Manifest Document No. 00005	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address US EPA Region 5 (Jefferson Processing) 4234 County Rd 74 77 W Jackson Blvd. Mingo Junction, OH 43938 Chicago Ill 60606		6. US EPA ID Number S C W 0 0 0 0 0 0 0 1 7		A. State Manifest Document Number		
4. Generator's Phone () 740-284-1515		8. US EPA ID Number		B. State Generator's ID		
5. Transporter 1 Company Name Safety-Kleen(TG) Inc.		10. US EPA ID Number G A D 9 8 0 8 3 9 1 8 7		C. State Transporter's ID		
7. Transporter 2 Company Name		12. Containers No. Type		D. Transporter's Phone 800-500-7824		
9. Designated Facility Name and Site Address Safety-Kleen(PPM) Inc. 1875 Forge St. Tucker GA 30084		13. Total Quantity		E. State Transporter's ID		
		14. Unit Wt/Vol		F. Transporter's Phone		
		1. Waste No.		G. State Facility's ID		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HM		12. Containers No. Type		H. Facility's Phone 800-500-7824		
a. X RQ, Polychlorinated Biphenyls, 9, UN2315, PGIII		0 0 1 TT		K		
b.				1.9.3.5.0		
c.						
d.						
J. Additional Descriptions for Materials Listed Above A. Oil Under 500ppm, In Tanker		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information In case of spill, dike and contain. Notify generator immediately. 24hr emergency response # 800 424 8802 Date removed from service for disposal 8-28-00						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimized the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name THOMAS COOK		Signature [Signature]		Month Day Year 08/27/00		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature [Signature]		Month Day Year 082800		
Printed/Typed Name TONY C BENTON		Signature [Signature]		Month Day Year 082800		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature [Signature]		Month Day Year 082800		
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space Rec'd 11a) 5670 gal (19278 Kg) @ a						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name David P. Campbell Signature [Signature] Month Day Year 0910/00						

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS*Item 1. Generator's U.S. EPA ID Number - Manifest Document Number*

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA))

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional,

new, or different information in this space. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode *other than* highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode *in addition to* the highway mode is used, enter the appropriate additional mode (e.g., *and rail*) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information *except* the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS*Item 17. Transporter 1 Acknowledgement of Receipt of Materials*

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES*Item 19. Discrepancy Indication Space*

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

PCB MANIFEST CONTINUATION SHEET

SAFETY-KLEEN

(PPM PCB SERVICES)

**MUST ACCOMPANY
ALL UNIT MANIFEST**

COMPANY NAME

JEFFERSON PROCESSING (US EPA REGION 5) PAGE

PAGE

O

MANIFEST DOCUMENT #

190005

DATE _____

8-28-00

[illegible]

I CERTIFY THAT WITH THE EXCEPTION OF WEIGHTS, THE ABOVE INFORMATION IS TRUE AND ACCURATE

GENERATOR SIGNATURE

GENERATOR PRINTED NAME

DATE _____

DISTRIBUTION - WHITE & YELLOW SAFETY-KLEEN, PINK GENERATOR



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 681

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/8/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00005

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	2271	7721.4

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: 
Robert J. Germon
Facility Manager



9/12/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 9/7/00
EPA ID # / Manifest: OHSFN0508038 / 00001
Job Control #: 00 - 690

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

07278 / 690

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O H S F N O 5 0 8 0 3 8	Manifest Document No. 000001	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address US EPA Region 5 (Jefferson Processing) 4234 County Road 74 Mingo Junction, OH 43938				A. State Manifest Document Number		
4. Generator's Phone () 740-284-1515				B. State Generator's ID		
5. Transporter 1 Company Name Safety-Kleen(TG) Inc.				C. State Transporter's ID		
7. Transporter 2 Company Name				D. Transporter's Phone 800-500-7824		
9. Designated Facility Name and Site Address Safety-Kleen(PM) Inc. 1875 Forge St. Tucker GA 30084				E. State Transporter's ID		
10. US EPA ID Number G A D 9 8 0 8 3 9 1 8 7				F. Transporter's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				G. State Facility's ID		
a. X RQ, Polychlorinated Biphenyls, 9, UN2315, PGIII				H. Facility's Phone 800-500-7824		
12. Containers				13. Total Quantity		
No. Type				Unit Wt/Vol Waste No.		
0 0 1 TT				K		
1.2273						
J. Additional Descriptions for Materials Listed Above A. Oil under 500ppm, In Tanker				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information In case of spill, dike and contain. Notify generator immediately. 24hr emergency response# 800 424 8802 Date Removed from service for disposal 8-26-00						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimized the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name THOMAS COOK		Signature [Signature]		Month Day Year 10 8 26 00		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature [Signature]		Month Day Year 10 8 26 00		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature [Signature]		Month Day Year 10 8 26 00		
19. Discrepancy Indication Space Rec'd 11a) 3456 gal (11,750 kg) @ [initials]						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name David H. Campbell		Signature [Signature]		Month Day Year 10 9 10 00		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	(including roll-offs)
TP = Tanks portable	CW = Wooden boxes, cartons, cases
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (WL/Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional,

new, or different information in this space. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments, destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate additional mode (e.g., and rail) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information except the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courthand St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

**MUST ACCOMPANY
ALL UNIT MANIFEST**

2

8-26-02

SECRET

GE. Ser#	C-65763C
----------	----------

71-E

10000

DATE _____

DISTRIBUTION - WHITE & YELLOW SAFETY-KLEEN, PINK GENERATOR



8/31/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 8/30/00

EPA ID # / Manifest: OHSFN0508038 / 00004

Job Control #: 00 - 673

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

07278 / 673

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O H S F N O 5 0 8 0 3 8		Manifest Document No. 00004		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.			
3. Generator's Name and Mailing Address US EPA Region 5 (Jefferson Processing) 4234 County Road 74 77 W. Jackson Blvd. Mingo Junction, OH 43938 Chicago Ill 60606						A. State Manifest Document Number					
						B. State Generator's ID					
4. Generator's Phone 740-284-1515						C. State Transporter's ID					
5. Transporter 1 Company Name Safety-Kleen(TG) Inc.						D. Transporter's Phone 800-500-7824					
7. Transporter 2 Company Name						E. State Transporter's ID					
9. Designated Facility Name and Site Address Safety-Kleen(PPM) Inc. 1875 Forge St Tucker, GA 30084						F. Transporter's Phone					
10. US EPA ID Number G A D 9 8 0 8 3 9 1 8 7						G. State Facility's ID					
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HM X RQ, Polychlorinated Biphenyls, 9, UN2315, PGIII						12. Containers		13. Total Quantity		14. Unit Wt/Vol	
						No. Type				I. Waste No.	
a.						0 0 1 TT		1.9.350		K	
b.											
c.											
d.											
J. Additional Descriptions for Materials Listed Above A Oil under 500ppm, In Tank						K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information In case of spill, dike and Contain. Notify Generator Immediately. 24hr emergency response# 1800 424 8808 Date removed from service for disposal 8-28-00											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimized the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name THOMAS COOK						Signature <i>[Signature]</i>			Month Day Year 10 8 28 00		
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name Rock Henderson			Signature <i>[Signature]</i>		
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name			Signature		
19. Discrepancy Indication Space Recd 11a) 5751 gal (19,553 gal)											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name Daniel P Campbell						Signature <i>[Signature]</i>			Month Day Year 10 8 30 00		

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases (including roll-offs)
DF = Fiberboard or plastic drums, barrels, kegs	CW = Wooden boxes, cartons, cases
TP = Tanks portable	CF = Fiber or plastic boxes, cartons, cases
TT = Cargo tanks (tank trucks)	BA = Burlap, cloth, paper or plastic bags
TC = Tank cars	
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional.

new, or different information in this space. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode *other than* highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode *in addition to* the highway mode is used, enter the appropriate additional mode (e.g., *and rail*) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information *except* the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office Management and Budget, Washington, DC 20503.

PCB MANIFEST CONTINUATION SHEET

SAFETY-KLEEN

(PPM PCB SERVICES)

**MUST ACCOMPANY
ALL UNIT MANIFEST**

COMPANY NAME

Jefferson Processing (US EPA Region 5)

PAGE

2

OF

2

MANIFEST DOCUMENT #

0330 4

DATE _____

8-28-00

[illegible]

I CERTIFY THAT WITH THE EXCEPTION OF WEIGHTS, THE ABOVE INFORMATION IS TRUE AND ACCURATE

GENERATOR SIGNATURE

GENERATOR PRINTED NAME

DATE _____

DISTRIBUTION - WHITE & YELLOW SAFETY-KLEEN, PINK GENERATOR



9/11/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 673

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 9/6/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00004

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	5751	19553.4

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By:


Robert J. Germon
Facility Manager



Safety-Kleen (Deer Park), Inc.
P.O. Box 609, Deer Park TX 77536
Phone 281-930-2300 Fax 281-930-3663

CONFIRMATION OF RECEIPT OF MANIFESTED WASTE

GENERATOR NAME/ADDRESS: US EPA Region 5 (Jefferson Proc.)
Mingo, Junction, OH. 43938
STATE MANIFEST DOCUMENT NO.: ROL 01234
DATE OF RECEIPT AT FACILITY: 8-29-00

Enclosed is your original, completely signed Manifest which indicates acceptance of material (with discrepancies as indicated, if any) by Safety-Kleen (Deer Park), Inc.

Elaine Burger
SK (Deer Park), Inc.
8-30-00
Date

TEXAS NATURAL RESOURCE
CONSERVATION COMMISSION
P.O. Box 13087
Austin, Texas 78711-3087

6 19 61 29
AU



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09/30/95

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O H S F N O 5 0 8 0 3 8		Manifest Document No. 00503		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address US EPA Region 5 (Jefferson Processing) 4234 County Road 74, 77 W. Jackson Blvd Mingo Junction, OH 43938 &740-284-1515				6. US EPA ID Number O K D 9 8 1 5 8 8 7 9 1		A. State Manifest Document Number ROL 01234			
4. Generator's Phone ()				7. Transporter 2 Company Name		B. State Generator's ID			
5. Transporter 1 Company Name Triad Transport				8. US EPA ID Number		C. State Transporter's ID			
9. Designated Facility Name and Site Address Safety-Kleen 2027 Battleground Rd Deerpark, TX 77536				10. US EPA ID Number T X D 0 5 5 1 4 1 3 7 8		D. Transporter's Phone 614-870-1619			
						E. State Transporter's ID			
						F. Transporter's Phone			
						G. State Facility's ID			
						H. Facility's Phone 281-930-2300			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	Type	13. Total Quantity	14. Unit Wt. Vol	I. Waste No.	
X	RO, Polychlorinated Biphenyls, 9, UN2315, PGIII			001	TT	19342	K		
	b.								
	c.								
	d.								
J. Additional Descriptions for Materials Listed Above A. PCB oil (ASKARAL) HO# 362808-550 CONFIRMATION# 235229						K. Handling Codes for Wastes Listed Above 11041			
15. Special Handling Instructions and Additional Information "PCB MANIFEST" In case of spill, dike and contain. Notify generator immediately. 24hr emergency response (800) 424-8802 Date Removed from service for disposal 8-26-00									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Thomas Cook				Signature <i>[Signature]</i>			Month Day Year 08 26 00		
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name Michael Clark				Signature <i>[Signature]</i>			Month Day Year 08 26 00		
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name				Signature			Month Day Year		
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name Heley Sawyer				Signature <i>[Signature]</i>			Month Day Year 08 26 00		

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

- (1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.
- (2) Enter the total number of pages used to complete this manifest.
- (3) Enter the company name and mailing address.
- (4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.
- (5) Enter the company name of the first transporter and their U.S. EPA ID Number.
- (6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).
- (7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.
- (8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**
- (9) Complete the waste description table as follows:
 - (A) **ITEM 11A** - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.
 - (B) **ITEM 11** - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.
 - (C) **ITEM 12** - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TNRCC Industrial Solid Waste Rules.
 - (D) **ITEM 13** - Enter the total quantity of waste described on each line.
 - (E) **ITEM 14** - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	
 - (F) **ITEM 1** - Enter the appropriate TNRCC State Waste Code for each waste you are shipping.
- (10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used; the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.
- (11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.
- * (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

- (1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.
- (2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.
- (3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".
- * (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD Facility Owner/Operator**.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/ OPERATOR (Please Type or Print Clearly)

- (1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.
- (2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.
- (3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TNRCC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TNRCC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

PROGRAM-ID: PTR2981B
RUN DATE : 9/08/00
RUN TIME : 11:33 AM

SAFETY-KLEEN (DEER PARK), INC.
CERTIFICATE OF DISPOSAL
005853


PAGE: 2

This completes the Certificate(s) of Destruction for manifest(s): TXROL01234

* Disposal Methods : 'I' - Waste that was incinerated. *
* 'L' - Waste that was landfilled. *
* 'O' - Offsite disposal. *
* 'C' - Offsite reclamation *
* *
* Disposal Facility : SAFETY-KLEEN (DEER PARK), INC. *
* P. O. BOX 609 *
* DEER PARK, TX 77536 *
* EPA ID : TXD055141378 *
* *

Under civil and criminal penalties of law for making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Please call (281) 930-2317 if there are any questions concerning the information on this Certificate of Disposal.



Authorized Agent
SAFETY-KLEEN (DEER PARK), INC.

PROGRAM-ID: PTR2981B

SAFETY-KLEEN (DEER PARK), INC.

RUN DATE : 9/08/00

CERTIFICATE OF DISPOSAL

RUN TIME : 11:33 AM

005853

PAGE: 1

Certificate of Disposal

Stream Order Manifest Received

Name and Address

Number Number Number Date

362808 235229 TXROL01234 8/29/00

US EPA REGION 5

4243 COUNTY ROAD 74

JEFFERSON PROCESSING

MINGO JUNCTION, OH 43938

Attn: THOMAS COOK

Inventory Customer's Unique CONTAINER Prd SHP Disposal
Cntrl Nbr Serial Number Type Contents Cd To Mthd Date

000235229 BULK550 LIQUID 550 I 9/05/00

Total Containers: 1



8/29/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Dear ENVIRONMENTAL MANAGER;

Enclosed you will find your signed copies of manifest which indicates acceptance of your PCB contaminated material at our Safety-Kleen (PPM), Inc. facility in Tucker, GA.

Date Received: 8/28/00

EPA ID # / Manifest: OHSFN0508038 / 00002

Job Control #: 00 - 663

Any inquiries should refer to your Safety-Kleen job control number. If you have any questions concerning this shipment, please contact me in our Tucker office at (770) 934-0902.

Sincerely,

Safety-Kleen (PPM), Inc.

Amy C. Daniel
Records Administrator

Attachments

cc: Charlie Keegan, Earth Tech, P.O. Box
28837, Richmond, VA 23228

07278/663

Emergency Contact Telephone Number

Please print or type
(Form designed for use on elite (12-pitch) typewriter.)

Form Approved OMB No. 2050-0039 Expires 9-30-99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. O H S F N O 5 0 8 0 3 8	Manifest Document No. 00002	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address US EPA Region 5 (Jefferson Processing) 4234 County Road 74 77 W. Jackson Blvd. Mingo Junction, OH 43938 Chicago Ill 60606		A. State Manifest Document Number		B. State Generator's ID	
4. Generator's Phone () 740-284-1515		C. State Transporter's ID		D. Transporter's Phone 800-642-1311	
5. Transporter 1 Company Name Enviroserve		6. US EPA ID Number OH D 9 8 6 9 7 5 3 9 9		E. State Transporter's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		F. Transporter's Phone	
9. Designated Facility Name and Site Address Safety-Kleen (PPM) Inc. 1875 Forge St Tucker GA 30084		10. US EPA ID Number G A D 9 8 0 8 3 9 1 8 7		G. State Facility's ID	
H. Facility's Phone 800-500-7824					
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. X HM RQ, Polychlorinated Biphenyls, 9, UN2315, PGIII		No. 0 0 1	Type TT	1.5205	K
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above A. Oil under 500ppm, In tanker		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information In case of spill, dike and contain. Notify generator Immediately. 24hr emergency response# (800) 424-8802 Date removed from service for disposal 8-26-00					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimized the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Thomas Cook		Signature <i>[Signature]</i>		Month Day Year 10/8/26/00	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name Jim Bishop		Signature <i>[Signature]</i>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature	
19. Discrepancy Indication Space Rec'd 11a) 4023 gal (13,678 kg) @cd					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name Jeff B. PLACEK		Signature <i>[Signature]</i>	
		Month Day Year 10/8/28/00			

UNIFORM HAZARDOUS WASTE MANIFEST AND INSTRUCTIONS EPA FORM 8700-22

U.S. EPA Form 8700-22

Read all instructions before completing this form.

This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used - press down hard.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to use this form (8700-22) and, if necessary, the continuation sheet (Form 8700-22A) for both inter- and intrastate transportation.

Federal regulations also require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage and disposal facilities to complete the following information:

GENERATORS

Item 1. Generator's U.S. EPA ID Number - Manifest Document Number

Enter the generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this Manifest (e.g., 00001) by the generator.

Item 2. Page 1 of -

Enter the total number of pages used to complete this Manifest, i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any.

Item 3. Generator's Name and Mailing Address

Enter the name and mailing address of the generator. The address should be the location that will manage the returned Manifest forms.

Item 4. Generator's Phone Number

Enter a telephone number where an authorized agent of the generator may be reached in the event of an emergency.

Item 5. Transporter 1 Company Name

Enter the company name of the first transporter who will transport the waste.

Item 6. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the first transporter identified in item 5.

Item 7. Transporter 2 Company Name

If applicable, enter the company name of the second transporter who will transport the waste. If more than two transporters are used to transport the waste, use a Continuation Sheet(s) (EPA Form 8700-22A) and list the transporters in the order they will be transporting the waste.

Item 8. U.S. EPA ID Number

If applicable, enter the U.S. EPA twelve digit identification number of the second transporter identified in item 7.

Note.-If more than two transporters are used, enter each additional transporter's company name and U.S. EPA twelve digit identification number in items 24-27 on the Continuation Sheet (EPA Form 8700-22A). Each Continuation Sheet has space to record two additional transporters. Every transporter used between the generator and the designated facility must be listed.

Item 9. Designated Facility Name and Site Address

Enter the company name and site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the company mailing address.

Item 10. U.S. EPA ID Number

Enter the U.S. EPA twelve digit identification number of the designated facility identified in item 9.

Item 11. U.S. DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA)]

Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste as identified in 49 CFR 171 through 177.

Note.-If additional space is needed for waste descriptions, enter these additional descriptions in item 28 on the Continuation Sheet (EPA Form 8700-22A).

Item 12. Containers (No. and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

Table I - Types of Containers

DM = Metal drums, barrels, kegs	CY = Cylinders
DW = Wooden drums, barrels, kegs	CM = Metal boxes, cartons, cases
DF = Fiberboard or plastic drums, barrels, kegs	(including roll-offs)
TP = Tanks portable	CW = Wooden boxes, cartons, cases
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags
DT = Dump truck	

Item 13. Total Quantity

Enter the total quantity of waste described on each line.

Item 14. Unit (Wt./Vol.)

Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table II - Units of Measure

G = Gallons (liquids only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic meters

Item 15. Special Handling Instructions and Additional Information

Generators may use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. States may not require additional.

new, or different information in this space. For international shipments, generators must enter in this space the point of departure (City and State) for those shipments destined for treatment, storage, or disposal outside the jurisdiction of the United States.

Item 16. Generator's Certification

The generator must read, sign (by hand), and date the certification statement. If a mode *other than* highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode *in addition to* the highway mode is used, enter the appropriate additional mode (e.g., *and rail*) in the space below.

Primary exporters shipping hazardous wastes to a facility located outside of the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgment of Consent to the shipment."

In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements.

Generators may preprint the words, "On behalf of" in the signature block or may hand write this statement on the signature block prior to signing the generator certifications.

Note.-All of the above information *except* the handwritten signature required in item 16 may be preprinted.

TRANSPORTERS

Item 17. Transporter 1 Acknowledgement of Receipt of Materials

Enter the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Item 18. Transporter 2 Acknowledgement of Receipt of Materials

Enter, if applicable, the name of the person accepting the waste on behalf of the second transporter. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Note.-International Shipments - Transporter Responsibilities.

Exports-Transporters must sign and enter the date the waste left the United States in item 15 of Form 8700-22.

Imports-Shipments of hazardous waste regulated by RCRA and transported into the United States from another country must upon entry be accompanied by the U.S. EPA Uniform Hazardous Waste Manifest. Transporters who transport hazardous waste into the United States from another country are responsible for completing the Manifest (40 CFR 263.10(c)(1)).

OWNERS AND OPERATORS OF TREATMENT, STORAGE, OR DISPOSAL FACILITIES

Item 19. Discrepancy Indication Space

The authorized representative of the designated (or alternate) facility's owner or operator must note in this space any significant discrepancy between the waste described on the Manifest and the waste actually received at the facility.

Owners and operators of facilities located in unauthorized States (i.e., the U.S. EPA administers the hazardous waste management program) who cannot resolve significant discrepancies within 15 days of receiving the waste must submit to their Regional Administrator (see list below) a letter with a copy of the Manifest at issue describing the discrepancy and attempts to reconcile it (40 CFR 264.72 and 265.72).

Owners and operators of facilities located in authorized States (i.e., those States that have received authorization from the U.S. EPA to administer the hazardous waste program) should contact their State agency for information on State Discrepancy Report requirements.

EPA Regional Administrators

Regional Administrator, U.S. EPA Region I, J.F. Kennedy Fed. Bldg., Boston, MA 02203

Regional Administrator, U.S. EPA Region II, 26 Federal Plaza, New York, NY 10278

Regional Administrator, U.S. EPA Region III, 6th and Walnut Sts., Philadelphia, PA 19106

Regional Administrator, U.S. EPA Region IV, 345 Courtland St., NE., Atlanta, GA 30365

Regional Administrator, U.S. EPA Region V, 230 S. Dearborn St., Chicago, IL 60604

Regional Administrator, U.S. EPA Region VI, 1201 Elm Street, Dallas, TX 75270

Regional Administrator, U.S. EPA Region VII, 324 East 11th Street, Kansas City, MO 64106

Regional Administrator, U.S. EPA Region VIII, 1860 Lincoln Street, Denver, CO 80295

Regional Administrator, U.S. EPA Region IX, 215 Freemont Street, San Francisco, CA 94105

Regional Administrator, U.S. EPA Region X, 1200 Sixth Avenue, Seattle, WA 98101

Item 20. Facility Owner or Operator: Certification of Receipt of Hazardous Materials Covered by This Manifest Except as Noted in Item 19

Print or type the name of the person accepting the waste on behalf of the owner or operator of the facility. That person must acknowledge acceptance of the waste described on the Manifest by signing and entering the date of receipt.

Items A-K are not required by Federal regulations for intra- or interstate transportation. However, States may require generators and owners or operators of treatment, storage, or disposal facilities to complete some or all of items A-K as part of State manifest reporting requirements. Generators and owners and operators of treatment, storage, or disposal facilities are advised to contact State officials for guidance on completing the shaded areas of the Manifest.

PCB MANIFEST CONTINUATION SHEET

SAFETY-KLEEN

PCB SERVICES

MUST ACCOMPANY

ALL UNIT MANIFEST

COMPANY NAME

US EPA REGIONS (JEFFERSON PROC.)

PAGE

2 OF 2

OF

2

MANIFEST DOCUMENT #

00002

DATE _____

8-26-00

[illegible]

Revised 12/28/2009



9/6/00

JEFFERSON PROCESSING
ENVIRONMENTAL MANAGER
4243 COUNTY ROAD 74
MINGO JUNCTION, OH 43938

Re: S-K Job ID # 00 - 663

Dear ENVIRONMENTAL MANAGER;

This is to certify material referenced below was decontaminated to less than 2ppm on 8/31/00, at our Tucker, Georgia facility - Safety-Kleen (PPM), Inc., GAD980839187, 1875 Forge Street, Tucker, GA 30084 - in accordance with 40CFR761.60(e), and PPM Inc.'s authorization from the U.S. Environmental Protection Agency in Washington, D.C.

EPA ID # / Manifest Number: OHSFN0508038 / 00002

<u>S-K ID Number</u>	<u>Total Gallons</u>	<u>Total Kilograms</u>
	4023	13678.2

Under civil and criminal penalties of the law for the making or submission of false or fraudulent statements or representations (18 U.S.C. 1001 and 15 U.S.C. 2615), I certify that the information contained in or accompanying this document is true, accurate, and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true, accurate, and complete.

Sincerely,

By: Robert J. Germon
Robert J. Germon
Facility Manager